TURN TEA SET PREVIOUS Approved or Release 2002/0	6/10 : CIA-RDP69B0	404R0001001	3000 <b>7</b> 4 <b>4</b> 5. 9-16
A Service of the serv	RET	DSA	9 OXC
	1 2 3		131
ROUMENA	15	The second section of the section of	52
TO ,   INTERCEDENT	(5)	and commercial that interest in the second contract is such a second contract of the second	3/
FROM : C' II''			
AGNON:			
SWO :	)		
25X1A IN 99361 WEAD NON	GSA 15	ED ST	
SECRET 070507Z CITE		CIR	25X1A
FRIORITY OXCART	I		
GEN BACALIS FROM:			25X1A

- 1. ON 127°S FLIGHT TODAY WE EXPERIENCED ANOTHER FAILURE WITH TYPE IG PACKAGE. CAMERA OPERATED FOR 50 SECONDS THEN FAILED.

  NUMEROUS ATTEMPTS TO RESTART ALSO FAILED. NO CHECKS HAVE BEEN MADE AS OF NOW OTHER THAN AN ELECTRICAL CHECK OF ATRCRAFT POWER TO PACKAGE; THIS WAS MADE PRIOR TO ENGINE SHUTDOWN AND WAS SATISFACTORY. CAMERA WOULD NOT OPERATE DURING THIS PERIOD.
- 2. WILL FLY 127 AGAIN TOMORROW WITH ANOTHER PACKAGE TO POSI-TIVELY ELIMINATE AIRCRAFT FACTOR. WILL ALSO REPLY PACKAGE G IN ARTICLE 129 TOMORROW IF PROBLEM DISCOVERED AND CORRECTED.
- 3. SPECIFICS WILL BE PROVIDED BY DCM AS SOON AS POSSIBLE. S E C R E T TOR: 070526Z SEP 67

SECRET

S COURSE CONTRACTOR CONTRACTOR A CONTRACTOR CONTRACTOR